

Three-Dimensional Analysis of Crack in Centrally Perforated Photoelastic Cylinders under Internal Pressure



C. T. Liu
AFRL/PRSM
Edwards AFB CA 93524-7680, USA

C. W. Smith
ESM Dept.
Virginia Polytechnic Institute & State
University
Blacksburg, VA 24061, USA

Distribution A: Approved for public release; distribution unlimited

Report Documentation Page			Form Approved OMB No. 0704-0188		
<p>Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.</p>					
1. REPORT DATE JUL 2004	2. REPORT TYPE	3. DATES COVERED -			
4. TITLE AND SUBTITLE Three-Dimensional Analysis of Crack in Centrally Perforated Photoelastic Cylinder under Internal Pressure			5a. CONTRACT NUMBER		
			5b. GRANT NUMBER		
			5c. PROGRAM ELEMENT NUMBER 2302		
6. AUTHOR(S) C Liu; C Smith			5d. PROJECT NUMBER 0378		
			5e. TASK NUMBER		
			5f. WORK UNIT NUMBER		
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Air Force Research Laboratory (AFMC),AFRL/PRSM,10 E. Saturn Blvd.,Edwards AFB,CA,93524-7680			8. PERFORMING ORGANIZATION REPORT NUMBER		
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)			10. SPONSOR/MONITOR'S ACRONYM(S)		
			11. SPONSOR/MONITOR'S REPORT NUMBER(S)		
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited					
13. SUPPLEMENTARY NOTES					
14. ABSTRACT The objectives of this study were to (1) Investigate the Effect of Crack Geometry and Location on the Crack Growth Behavior in Centrally Perforated Cylinders under Internal Pressure. (2) Determine the Safety Factor for a Two-Dimensional Analysis of a Deep Part-Through crack.					
15. SUBJECT TERMS					
16. SECURITY CLASSIFICATION OF: a. REPORT b. ABSTRACT c. THIS PAGE unclassified unclassified unclassified			17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES 16	19a. NAME OF RESPONSIBLE PERSON




Objectives

- **Investigate the Effect of Crack Geometry and Location on the Crack Growth Behavior in Centrally Perforated Cylinders under Internal Pressure.**
- **Determine the Safety Factor for a Two-Dimensional Analysis of a Deep Part-Through crack.**



Specimen Geometries





Part-Through Crack

All dimensions in mm




Specimen Dimensions and Crack Locations



* Path of crack to maximum depth




Fringe Patterns Near Critical Loci at Fin Tip






Contour Plot of Stress σ_{yy} (No Crack)




Distribution A: Approved for public release; distribution unlimited



Two-Dimensional Crack Growth Tests




A




B



Two-Dimensional Crack Growth Tests

**A**

Crack initiated at the center of the fin

**B**


Crack initiated at the corner of the fin



Photoelastic Fringe Patterns




**Crack Turning
Completed**



**Crack Turning
Incomplete**




Typical Off-Axis Inclined Crack Which is Perpendicular to the Fin Surface





Typical Off-Axis Straight Crack Which is Parallel to the Fin Axis



Fin surface


C - crack front

D - camera view of the photograph

Magnification factor: 1.73



Typical Symmetric Crack Which is Near the Fin Axis




**a_0 - initial crack
 a - final crack**

M.F 2.52



Top and Edge Views of Crack




MDZ – Material Damage Zone
EVC – Edge View of Crack



Fringe Patterns near the Tip of a Symmetric Crack



Center Slice ($t = 4.29 \text{ mm}$)



P_{sf} $2.3 \times 10^{-2} \text{ MPa}$

c_f 175.30 mm

a_f 19.6 mm

Distributic Data zone: $(r_{ave})_2 - (r_{ave})_1 = 4.2635 - 0.4564 = 3.807 \text{ mm}$ imited



Summary of Mode I Stress Intensity Factor K and Normalized Mode I Stress Intensity Factor F



	a	c	a/c	a/t	Psf	K	F
Test 3A	15.38	30.74	0.50	0.41	.033	0.31	1.67
Test 5B	14.60	181.65	0.04	0.41	.041	0.74	2.49



Conclusions

- When the crack is perpendicular to the fine surface, a significant three-dimensional effect occurs during crack turning.
- When the crack is either parallel to or in the fin axis, there is no crack turning observed and the crack grows under normal mode only.
- During crack turning crack grows under normal and shear modes.
- For a same a/t ratio the Mode I stress intensity factor for the long crack is much higher than that of the part-through crack.
- The two-dimensional analysis of the deep part-through crack yields a safety factor of 1.49.
- The practice of using two-dimensional analysis to determine the criticality of a deep part-through crack is conservative.